Armstrong Shock Catalog

Courtesy Peter Caldwell

World Wide Auto Parts

http://www.nosimport.com/shoxcatalog.htm

The shock 6075 and 8002 are externally identical. The number we use is the Armstrong number stamped on the underside of each shock casting on the fronts. (on the rears, the number is stamped on the lower edge of a mounting boss)

Internally, the valve springs change wire diameter by a few thousandths. Not terribly significant, and honestly, probably not as noticeable as a change t radial tires from bias ply.

The screws are not the difference. Armstrong had running changes in manufacture over the years going from slotted to posidrive to Phillips screws all on the same part number. There is usually a date code on the front shocks into the 1980s. The valve nut (7/8") also changes over the years as does the seat in the body.

Both the BMC and the Armstrong numbers are stamped on the shock base

YEAR	MODEL	front			rear		
		TYPE	STANDARD	& HEAVY DUTY	TYPE	STANDARD	& HEAVY DUT
1959-60	AUSTIN—continued A.55 Cambridge Export C.K.D.—Australia	L	6945-IS9/10		L	6056/1-DAS9 Link 7382	
1961	A.55 Countryman Export and C.K.D.— Australia	L	8002-159/10		L	7584-DAS9 Link 7382	Adjustaride 7584-ADJ
1961-63	A.55 Saloon Mk.II A/R (Argentine)	L	7396-1S9/10		L	7584-DAS9 Link 7382	
1961-63	A.55 Pick-up ADO-49 A/R (Argentine)	L	7396-IS9/10		L	6939-DAS9 Link 7940	
1962-69	A.60 Saloon and Countryman from C/No. HS9/101	L	8181/1-IS9/10T		L	8182-DAS9T Link 7382	
1956-59	A.95 (BS.6)—RH 27897-76474; LH28274- 77444	L	6136-159/10		L	6891-DAS10 Link 6890	
1956-59	A.105 (BS,7)—RH.27897-76757; LH28274-76229	L	6136-159/10		L	6891-DAS10 Link 6890	
1959-61	A.99 RHD from C/No. ABS.9/101; LHD from C/No. ABS.9/105	L	7272/2-IS9/10 Stabilizer Link 7566		L	7424-DAS10 Link 7423	Adjustaride 7424-ADJ
1962-64	A.110 from C/No. HS.10/101	L	8189/1- 59/10		L.	8176-DAS10 Link 7423	
1964-67	A.110 Mk.II	L	8682-159/10		Т	65-0600.A (AT10-3190)	
1952-59	DS.6 Princess L.W.B. Saloon and DM.4 Princess L.W.B. Limousine 10142 on	L	6599-IS12 Special Order Only		L	6072-DAS12/2 Link 5564	
1956-59	DS.7 Princess Saloon 12986-13856 RHD only	L	6599-IS12 Special Order		L	6593-DAS12 Link 6595	
1956-59	DM.7 Princess Limousine 12986-13870		Only			Lina 6000	
1954-59	Healey 100-221579 on RHD	L	6075-IS9/10		L	6076-DAS9 Link 6321	Adjustaride 6076-ADJ
1954-59	Healey 100-221536 on LHD						
1955-57	Healey 100.S-AHS.3501 on	L	6403-IS9/10		L	6189-DAS10 Link 6321	
1958-59	Healey Sprite—up to 4332 (plus 4471, 4622, 4680,4684)	L	5925/1-IS9/3		L	7835-DAS9 Link 7848	
1959-61	Healey Sprite—from 4333 (exc. 4471, 4622, 4680, 4684)	L	5925/1-IS9/3	R.5925/4-IS9/3	L	7401-DAS9 Link 7433	R.7537-DAS9 Adjustaride 7401-ADJ
1961-64	Healey Sprite Mk.II from C/No. HAN.6, 101 RHD; HAN.6L.101 LHD						
1964-69	Healey Sprite Mk. III & IV—from C/No. HAN.8 38829	L	5925/1-IS9/3 Stab Link 8650	R.5925/4-1S9/3	L	8681-DAS9 Link 8407	R.8681/1-DAS9 Adjustaride 8681-ADJ
1959-61	Healey '3000' (BN.7 and BT.7) from C/No. 501	L	6075-IS9/10	R.7763-IS9/10	L	6076-DAS9 Link 6321	R.6076/1-DAS9 Adjustaride 6076-ADJ*
1961-62	Healey '3000' Mk. II						
1962-64	Healey '3000' Mk. II—Wire wheel only (BT.7 from C/No. 17129, BN.7 from C/No. 17236 to C/No. H.BJ.826704)	L	8002-159/10	R.8627-IS9/10	L	6076-DAS9 Link 6321	R.6076/1-DAS9 Adjustaride 6076-ADJ*
1964-68	Healey '3000' Mk. III from C/No. H.BJ.826705	L	8002-159/10	R.8627-IS9/10	L	8188-DAS10 Link 7928	R.8188/1-DAS10 Adjustaride 8188-ADJ
1959-61	Lancer Ser. II (Australia)	L	7200-IWS10		L	7397-DAS9 Link 7409	
1956-60	DH.1 and 2 Hearse, DA.1 and 2 Ambulance	L	6048-IS12 (Special Order Only)		L	6071-DAS12/2 Link 3118	
1961–69	DH.3 Hearse and DA.3 Ambulance	L	6599-IS12 (Special Order Only)		L	6072-DAS12/2 Link 5564	
		*Ad	aptor Plates requ	uired	I		